




KX-HDV130
192.168.0.36
Panasonic
KX-HDV130
Status
Network
System
VoIP
Telephone
Maintenance
SIP Settings
Web Port Close
VoIP
SIP Settings
- Line 1
- Line 2
VoIP Settings
- Line 1
- Line 2
User Agent
User Agent
Panasonic-{MODEL}/{fwver} ({mac})
NAT Identity
Enable Rport (RFC 3581)
Yes
No
Enable Port Punching for SIP
0
seconds [10-300, 0: Disable]
Enable Port Punching for RTP
0
seconds [10-300, 0: Disable]
Save
Cancel


KX-HDV130
192.168.0.36
Panasonic
KX-HDV130
Status
Network
System
VoIP
Telephone
Maintenance
SIP Settings [Line 1]
Web Port Close
VoIP
SIP Settings
- Line 1
- Line 2
VoIP Settings
- Line 1
- Line 2
Basic
Phone Number
Registrar Server Address
Registrar Server Port 5060 [1-65535]
Proxy Server Address
Proxy Server Port 5060 [1-65535]
Presence Server Address
Presence Server Port 5060 [1-65535]
Outbound Proxy Server Address
Outbound Proxy Server Port 5060 [1-65535]
Service Domain
Authentication ID
Authentication Password
Advanced
SIP Packet QoS (DSCP) 0 [0-63]
Enable DNS SRV lookup Yes No
SRV lookup Prefix for UDP _sip._udp.
SRV lookup Prefix for TCP _sip._tcp.
SRV lookup Prefix for TLS _sips._tcp.
Local SIP Port 5060 [1024-49151]
SIP URI
T1 Timer 500 milliseconds
T2 Timer 4 seconds
REGISTER Expires Timer 3600 seconds [1-4294967295]
Enable Session Timer (RFC 4028) 0 seconds [60-65535, 0: Disable]
Session Timer Method INVITE UPDATE INVITE/UPDATE
Enable 100rel (RFC 3262) Yes No
Enable SSAF (SIP Source Address Filter) Yes No
Enable c=0.0.0.0 Hold (RFC 2543) Yes No
Transport Protocol UDP TCP TLS
TLS Mode SIPS SIP-TLS


KX-HDV130
192.168.0.36
Panasonic
KX-HDV130
Status
Network
System
VoIP
Telephone
Maintenance
Web Port Close
VoIP Settings
VoIP
SIP Settings
- Line 1
- Line 2
VoIP Settings
- Line 1
- Line 2
RTP
RTP Packet Time
20
milliseconds
Minimum RTP Port Number
16000
[1024-59598: Even Number Only]
Maximum RTP Port Number
20000
[1424-59998: Even Number Only]
Telephone-event Payload Type
101
[96-127]
Voice Quality Report
Server Address
Port
5060
[1-65535]
Enable PUBLISH
Disable
Alert Report Trigger
Warning
Critical
Threshold MOS-LQ (Critical)
0
[0-40]
Threshold MOS-LQ (Warning)
0
[0-40]
Threshold Delay (Critical)
0
milliseconds [0-2000]
Threshold Delay (Warning)
0
milliseconds [0-2000]


KX-HDV130
192.168.0.36
Panasonic
KX-HDV130
Status
Network
System
VoIP
Telephone
Maintenance
Web Port Close
VoIP Settings [Line 1]
VoIP
SIP Settings
- Line 1
- Line 2
VoIP Settings
- Line 1
- Line 2
Basic
G.722
Enable
Yes No
Priority
1
[1-255]
PCMA
Enable
Yes No
Priority
1
[1-255]
G.729A
Enable
Yes No
Priority
1
[1-255]
PCMU
Enable
Yes No
Priority
1
[1-255]
DTMF Type
RFC2833 Inband SIP INFO
Advanced
RTP Packet QoS (DSCP)
0
[0-63]
RTCP Packet QoS (DSCP)
0
[0-63]
Enable RTCP
Yes No
Enable RTCP-XR
Yes No
RTCP&RTCP-XR Interval
5
seconds [5-65535]
SRTP Mode
SRTP RTP/SRTP
Enable Mixed SRTP&RTP by Conference
Yes No
Enable Mixed SRTP&RTP by Transfer
Yes No